Oil Field Environmental Incident Summary

Date/Time of Notice: 02/09/2014 13:36 Incident: 20140209134654 Responsible Party: Bridger Transfer LLC Well Operator: Well Name: Field Name: Well File #: 0 Date Incident: 2/8/2014 Time Incident: 1742 Facility ID Number: **WILLIAMS Sec:** 5 County: **Twp:** 155 **Rng:** 95 Location Description: Longitude: 102.915542 Latitude: 48.281075 Submitted By: Keith Hanson Received By: Keith Hanson Contact Person: 35701 Hwy 2 W Berthold, ND 58718 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil **Distance Nearest Occupied Building:** Distance Nearest Water Well: Type of Incident: Valve/Piping Connection Leak Release Contained in Dike: Yes - Within Dike Reported to NRC: Unknown Spilled **Units** Recovered Units Followup **Units** 0 Oil 10 barrels barrels **Brine** 0 barrels 0 barrels Other 0 barrels barrels **Description of Other Released Contaminant:** Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation: N/A

Tuesday, January 24, 2017

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Leakage was stopped then the spill was contained with the burm around the tanks. The spill was recovered by environmental company USES.

Wastes Disposal Location: By USES

Agencies Involved:

Updates

Date: 2/10/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release reported to be contained in the tank diking. This appears to be a duplicate report of one that was submitted through the NDDoH EIR. Followup is necessary.

Date: 3/30/2015 Status: Reviewed - No Action Required Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Duplicate report. See incident #2196 in General Environmental Incident reports for inspection.